





**Hole drilled for
POL pipe hanger
support through
pier deck.**

**Location of hole
being drilled**





**Location of
electrical lines
entry into vault**



**Cables viewed
inside vault from
outside vault
cover topside.**



**Drill bit burnt
from High
Voltage contact**